Made in the USA



SURGI-COLOR GUARD™

Not Made with Natural Rubber Latex

TUBULAR ELASTIC NET "ALERT" SYSTEM



Make Patient Safety a Priority with Color Coded Security.

- DO NOT CHANGE DRESSING!
- NO BLOOD PRESSURE CHECK HERE!
- NO BLOOD DRAWS HERE!
- NO INTRAVENOUS INJECTION HERE!
- REVIEW PHYSICIANS INSTRUCTIONS BEFORE PROCEEDING!



Product #	Color	Working Stretch
MTSCGR02	Red/White	7 inches
MTSCGR04	Red/White	20 inches
MTSCGR06	Red/White	27 inches
MTSCGR08	Red/White	40 inches

25 Yards per Box - 10 Boxes per Case



(800) 333-0109 www.medi-techintl.com

Make "PATIENT SAFETY" a **Priority with Color-Coded Security**

Latex-Free Tubular Dressing ALERT SYSTEM (From the Makers of SPANDAGE [™] Tubular Elastic Retainer Net)





Order #

MTSCGR08

8



S T O P !!!

Review Physicians Instructions Before Proceeding

DO NOT CHANGE DRESSING **Product Description (Suggested Use)** Size MTSCGR02 2 Medium Fingers/Toes, X-Small Arm/Hand, Small Hand, X-Small Leg/Foot MTSCGR04 4 Medium Arm/Hand, Large Hand, Medium Leg/Foot MTSCGR06 6 Small Head, Medium Shoulder, Medium Thigh, Large Leg/Foot

Large Head, Medium Chest/Back, Medium Axilla/Perineum, X-Large Thigh

Today's "Specialty" Advanced Wound Care Dressings need to be in place 5 to 7 Days or more to be Effective



Use SURGI-COLOR Guard[™] As an "ALERT SYSTEM" TO KEEP "SPECIALTY" WOUND CARE DRESSINGS IN PLACE

Any Nurse or HealthCare Provider (regardless of Shift Changes) will recognize that The RED Netting over the Dressing means to Review Physicians Instructions before Proceeding!!!

.04 Cents for a 3" piece of Size 2 - .45 Cents for a 12" piece of Size 8 adds a layer of protection

MEDICARE NO Longer Pays for Mistakes and/or Re-Do's

MEDI-TECH INTERNATIONAL CORP. 26 COURT STREET - SUITE 1301, BROOKLYN, NY 11242 - 800-333-0109 - www.medi-techintl.com



Surgi-Color Guard™

Case Study 1

(Figure #1)

This patient skin graft to the lower extremity was partially removed when the dressing was prematurely removed on post-op day 2. The dressing should have been left in place for 5 days allowing the graft to adhere to the wound bed. The patient graft subsequently failed and required a second skin graft operation.



Figure #1

(Figure #2) The patient second graft healed well.



Figure #2

Overall:

The patient required a second operation and an extended hospital stay for 5 days. The error of removing the dressing prematurely resulted in an additional \$15,000 on the patient's hospital bill.

Quantifiable Value:

Using Surgi-Color GuardTM on the extremity would have prevented this mistake and decreased the financial cost associated with this type of peri-operative error.

Study provided by Alfred T. Mitchell M.D.

Medi-Tech International Corp. 26 Court Street – Suite 1301, Brooklyn, NY 11242 718-875-4535 • 800-333-0109 www.medi-techintl.com